

===== 2014.01.01 00:00:14 remo-con disconnect=====  
Packet: P3X\_FW\_V01.10.0090.bin  
Upgrading ...  
Result: Failed.  
Reboot the aircraft and try to upgrade the firmware again.

===== 2014.01.01 00:00:15 remo-con disconnect=====  
Packet: P3X\_FW\_V01.10.0090.bin  
Result: Failed.  
Reboot the aircraft and try to upgrade the firmware again.

===== 2014.01.01 00:00:13 remo-con disconnect=====  
Packet: P3X\_FW\_V01.11.0020.bin  
Upgrading ...  
Result: Failed.  
Reboot the aircraft and try to upgrade the firmware again.

===== 2014.01.01 00:00:12 remo-con disconnect=====  
Packet: P3X\_FW\_V01.11.0020.bin  
Result: Failed.  
Reboot the aircraft and try to upgrade the firmware again.

===== 2014.01.01 00:00:15 remo-con disconnect=====  
Packet: P3X\_FW\_V01.11.0020.bin  
Result: Failed.  
Reboot the aircraft and try to upgrade the firmware again.

===== 2014.01.01 00:00:16 remo-con disconnect=====  
Packet: P3X\_FW\_V01.11.0020.bin  
Result: Failed.  
Reboot the aircraft and try to upgrade the firmware again.

===== 2014.01.01 00:00:14 remo-con disconnect=====  
Packet: P3X\_FW\_V01.11.0020.bin  
Result: Failed.  
Reboot the aircraft and try to upgrade the firmware again.

===== 2014.01.01 00:00:14 remo-con disconnect=====  
Packet: P3X\_FW\_V01.11.0020.bin  
Result: Failed.  
Reboot the aircraft and try to upgrade the firmware again.

===== 2017.11.13 17:42:19 =====  
Packet: P3X\_FW\_V01.11.0020.bin  
Result: Failed.  
Reboot the aircraft and try to upgrade the firmware again.

===== 2017.11.13 18:36:53 =====  
Packet: P3X\_FW\_V01.11.0020.bin

Result: Failed.

Reboot the aircraft and try to upgrade the firmware again.

===== 2017.11.13 18:40:50 =====

Packet: P3X\_FW\_V01.11.0020.bin

Result: Failed.

Reboot the aircraft and try to upgrade the firmware again.

===== 2014.01.01 00:00:15 remo-con disconnect=====

Packet: P3X\_FW\_V01.11.0020.bin

Result: Failed.

Reboot the aircraft and try to upgrade the firmware again.